

http://www.ijmp.jor.br v. 10, n. 1, January - February 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

# APPLICATION OF A PROPOSED TLS MODEL IN A LEAN PRODUCTIVE SYSTEM

Rui M.F.Dias A&I, Portugal rdias1263@hotmail.com

Luis Diogo Silva UNIDEMI,FCT,UNL, Portugal Id.silva@campus.fct.unl.pt

Alexandra Tenera
UNIDEMI,FCT,UNL, Portugal
abt@fct.unl.pt

Submission: 23/04/2018 Revision: 08/05/2018 Accept: 25/07/2018

#### **ABSTRACT**

The current market, becoming more rigid, forces companies to search continuously for innovation and improvement of their processes and products as a way to keep competitive and gain strategic advantages. Due to the global economic crisis, more and more companies try an approach through new management methodologies that allow better performances in terms of earning, profit and cost reduction. The present article proposes an integrated TOC (Theory of Constraints), Lean and Six-Sigma (TLS) model, with the objective of improving continuously a productive system, although it shows flexibility to be applied in other kinds of systems. The model synergistically integrate the best practices found in existing TOC, Lean and Six-Sigma models. The proposed model derivatives mainly from Eliyahu Goldratt's TOC model of the "5 focus steps" and TLS model "Ultimate Improvement Cycle", developed by Bob Sproull. The proposed TLS model was tested on an important Portuguese Manufacture. The implementation of a first continuous improvement cycle was completed and a second cycle began. The main results obtained by the implementation of the TLS model were extremely satisfactory.





http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

Keywords: Continuous Improvement; TOC; Lean; Six-Sigma; TLS

1. INTRODUCTION

The XX century was of extreme importance to the industrial world where three big production paradigms arised and which are still decisive in the way managers administer industrial plants and their processes till nowadays (JACOBS; CHASE; AQUILANO, 2009).

From those new paradigms, came some new methodologies that through continuous improvement cycles can create satisfactory results on productive system's performances. Current studies prove that the most effective continuous improvement systems in terms of costs reduction are gaining market share and improving quality currently are the models that combines the Theory of Constraints, Lean and Six-Sigma methodologies (PIRASTEH; FARAH, 2006; SPROULL, 2009).

Those models are known as TLS models.

On this paper, one TLS model is presented and the results of the proposed model tested in a real Lean productive system are shown. The model was built after reviewing each methodology by itself and the TLS existing models. Then, the three main classic improvement methodologies were compared and the converging characteristics were analysed, in order to make them merge synergistically.

A brief exploitation was made of the existing integrative TLS models and the best practises found on each model were resorted to be able to build a logic model. The main objective of creating a continuous improvement model was to improve an existing Lean productive system of an important Portuguese manufacturer.

The best state of the art found during the review of the models, which integrate the Theory of Constraint, Lean and Six Sigma, use TOC to focus and identify system constraints and some Lean and Six Sigma (LSS) tools which are mainly utilized to eliminate waste and reduce variability in the constraint step.

# 2. BRIEF THEORETICAL REVIEW ON CONTINUOUS IMPROVEMENT SYSTEMS

The biggest goal of continuous improvement systems is to concretize all the objectives defined by an organization in a systematic, consistent and gradual way (PEREIRA; REQUEIJO, 2012).



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

### 2.1. Theory of Constraints

TOC was developed firstly as an Optimized Production Timetables scheduling software in 1979 and five years latter its model was conceptualized on the bestseller "The Goal" by Goldratt and Cox (GOLDRATT; COX, 2004). The basic concept of TOC is often introduced through the chain analogy, where the chain is only as strong as its weakest link. So, any improvement that does not improve the performance of the weakest link most likely will not improve the system and can be considered waste (DAVIES; MABIN, 2009).

TOC is more than a system to find constraints; TOC is a continuous improvement system to improve and manage the system constraint performance in the global context, trying to achieve overall system improvement and not just localized improvements. TOC is a system focus, first on the system's leverage points (constraints) and then on how all parts of the system that impact on the operation of the leverage points.

Constraints could be physical if the issue is related to equipment, materials or resources or politics if caused by the market, policy of management, roles, standards or measures (LUCAS; TENERA, 2014).

The TOC evolved from the production planning technology to a system of managing tools that integrates the areas of logistics, production, project management, finances, accounting, performance measurement, distribution and supply chain, marketing, sales and problem resolution (COX; SCHLEIER, 2010).

The TOC as a methodology of continuous improvement uses a set of tools that aim to promote and elevate the performance of the systems, grouped in Table 1 in four main quadrants:



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

Table 1: Schematic Synthesis of TOC

	Prescriptive component	Reflective component
	Concepts and principles	Analysis and problem solving
	Conceptual principles	Logical tools:
		Current Reality Tree (CTR)
Έ	Prescriptions:	Conflict Resolution Diagram (CRD) or
one		Evaporating Cloud (EC)
ă E	The three basic questions	Future Reality Tree (FRT)
Strategic component	The five fundamental steps	Negative branch (NBR)
egic	The six levels of resistance	Pré- Requesites Tree (PRT)
trat		Transition Tree (TT)
\overline{\sigma}		
		Validation Principles:
		CategoriesLegitimate Reserve (CLR)
1	Specific Logical Applications	Measures of performance evaluation
la la		
M E	Drum - Buffer - Rope (DBR)	Throughput (T)
ပိ	Critical Chain (CC)	Investment (I)
na l	Buffer management (BM)	Operational Expenses (OE)
Operational Component	Analyzes V-A-T	
ber		
0		

Source: adapted from Tenera, (2006)

- First quadrant concepts and principles that define the strategic and prescriptive component of TOC;
- Second quadrant analysis and problem solving tools;
- Third quadrant operational and prescriptive where logical applications are proposed to apply to certain specific systems;
- Fourth quadrant performance evaluation measures.

In the model presented in this paper we use two different tools of TOC methodology

• Five Focusing Steps - Figure 1




Figure 1: Goldratt's five focus steps model



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

The five steps can be briefly described as (TENERA, 2006; PRETORIUS, 2014).

- a) Identify the system's constraint It's identified which process or processes limit all system's performance;
- b) Decide how to exploit the constraint It should be answered to the question: "How to make the constraint the most efficient possible? At this moment it's not resourced to financial investments and the constraint should be "squeezed" at his full potential.
- c) Subordinate everything else to the above decision This step insurances that all the other as processes work in order to support the constraint even if through losing some of its own capacity. The recommended tool to be applied on this step is DBR.
- d) Elevate the system's constraint The constraint's performance is potentiated.
   One way to improve is by investing in new resources.
- e) Evaluate constraint It's verified in this step if the capacity of the constraint is now superior to demand this means if the constrain has been broken. In that case the improvement cycle closes and returns to step 1 but can't allow inertia to become the new system constraint. Otherwise returns to step 4 and elevates the capacity until the process is no longer the constraint.
- Drum Buffer- Rope (DBR) Figure 2




Figure 2: Drum-Buffer-Rope Source: adapted from Tenera, (2006)

DBR promotes the constitution of strategic reserves (Buffer) in order to protect the Constraint (Drum) and the synchronization of the flow through logistic mechanisms of alert (Rope).

DBR is a hybrid method of programming production, where the materials and components are pushed into the production system through a system of communication called rope, which aims to guarantee the supply of the buffer that



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

allows the fluctuations that can occur in the productive flow do not affect the performance of the constraint, drum. (Tenera, 2006)

#### 2.2. Lean Production

Lean appeared in the middle of XX century in Toyota associated with the bigger complexity of processes. It covers since the conception and develop of products, supply of materials, tools and components, productive processes until the commercialization of products.

The emphasis of this methodology is given to the optimization of processes, seek or elimination of non-value activities and on generation of value to stakeholders (PIRASTEH; FOX, 2010).

According to Womack and Jones there are 5 principles that define Lean (WOMACK; JONES, 1996):

- a) Define Value from the perspective of the final costumer;
- b) Identify the completed chain of value for each product or family of products and eliminate waste;
- c) Take actions that make flow the activities that generate value;
- d) Pull production to clients demand, this mean provide what the customer wants, when he wants;
- e) Pursue perfection.

Identification and elimination of waste is the most fundamental aspect to an organization that implements Lean. In Toyota's production system, Shigeo Shingo identifies 7 *Muda* that correspond to the biggest wastes that don't add value to the costumer, as show and described on *Table 2* (PACHECO, 2014):

Table 2: Identification and description of the 7 Muda

Muda	Recommended Lean Tools	
Overproduction  Producing something when it's not needed. Results in excess of inventory, resources, energy and materials utilization. Generates loss of planning flexibility.		- Takt Time - Kanban - SMED
Defects	Production that needs reprocessing or being eliminated. It's caused by lack of quality, low performance or human failures. Causes productivity decrease.	- <i>Jidoka</i> - <i>Poka-Yoke</i> - Standard Work
Unnecessary inventory	Having a quantity of inventory superior to the immediate needs, causes the unnecessary costs of material possession and lower costumer's service rate.	- Just-in-time - <i>Heijunka</i> - Pull system
Inappropriate Results in incompatibilities between the necessa processing processes and tools to make a product.		- Kaizen



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

Excessive transportation	Can be reduced by layout changing, transportation system or alteration to a production cell.	- VSM - Continuous flow
Waiting	Inactivity for a long period due to operators and material and lack of information can result in a poor flow and increasing of Lead Time.	- Standard Work - <i>Heijunka</i> -SMED
Unnecessary motion	Bad organization of workplaces due to weak ergonomics, lack of formation or demotivation of operators and inappropriate layout.	- 5S -VSM

#### 2.3. Six-Sigma

Six-Sigma was developed initial by Motorola executives in the late 1980s then some years later, it was exploited and developed by General Electric, Honeywell and others companies (TENNANT, 2001).

Six-Sigma is defined as a "business strategy used to improve business profitability, to improve the effectiveness and efficiency of all operations to meet or exceed customer's needs and expectations".

Applied for the first time in manufacturing operations, it rapidly expanded to different functional areas such as marketing, engineering, procurement, services, and administrative support, as organizations perceived its benefits, especially when they associated financial returns and cost reduction with implementation of Six Sigma (PACHECO, 2014).

The methodology statistic basis is to try to optimize processes until an efficiency rate of 99, 99966%, where a process must not produce more than 3.4 defects per million opportunities.

The Greek letter  $\sigma$  (Sigma) correspond to a standard deviation of process variability so in Six-Sigma it is intended that all processes own a variability inferior to six standard deviation compared to the average of the process.

The most common improvement cycle used to apply Six-Sigma is the DMAIC cycle as shown at *Figure 3*. Each phase of the cycle and the recommended tools to apply in every of the five phases are shown at *Table 3* (KHANDEKAR; SULAKHE, 2014):



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830




Figure 3: DMAIC cycle

Table 3: DMAIC cycle phases, description and tools used

	Beautifier	Recommended Six-
Phase	Description	Sigma Tools
	Define with precision the project where are identified	- Project Charter
	the objectives and the scope. It is chosen a team	<ul> <li>VOC (Voice of</li> </ul>
Define	and decided the timeline. It's important to define the	Client)
	priorities of the client in matters of what he considers	-Run Chart and
	to have most impact on quality.	Flowchart
	Define the baseline of the project, so the location or	
	focus of the problem. It is defined the metrics to	<ul> <li>Pareto chart</li> </ul>
Measure	evaluate and the criteria of rejection in the inspection	<ul> <li>Control chart</li> </ul>
	method. Data of the system is collected and	<ul> <li>Gage R&amp;R study</li> </ul>
	analysed.	
	For the main problems that cause variability in the	- Ishikawa diagram
Analyse	processes, the critical factors and the root causes	- DOE (Design of
	that are the origin of the variability are identified. It is	Experiences)
	searched the tools that are able to continuously	- FMEA Matrix
	improve the process more easily.	- ANOVA
	It's proposed, evaluated and implemented solutions	- Brainstorming
Improve	to each problem found in a way to eliminate defects	<ul> <li>Opportunities</li> </ul>
Improve	and improve the process respecting the needs of the	Flowchart
	client.	- 5 Whys
	Ensure that the solutions are reached with success	- Control Charts
Control	and maintain sustained at long term. The	- Hypothesis Tests
Control	improvements should but standardized and the	- Audits
	statistic control of processes must be implemented.	- Addits

# 2.4. Integration of Theory of Constraints, Lean and Six Sigma

All continuous improvement methodology brings competitive advantages by itself for any company's system.

The importance of the three philosophies, up until now described, the gains and successes obtained with them, created in the users and researchers the necessity to evaluate if the complementarity between the methodologies may fill the individual weaknesses of each one and improve the system performance.



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

These investigations, more than evaluating convergences and complementarities, have essentially sought to integrate the three methodologies, and creating more consistent models that promote the continuous improvement of organizations.

Controlled experiences on real industrial plants demonstrate that is possible to obtain more considerable improvements when combining TOC five focus step model with Lean and Six-Sigma, compared with applying each methodology isolated (PIRASTEH; FARAH, 2006).

It's possibly to increase the market share and without spending money due to the benefits that Lean and Six-Sigma can bring integrated with the Theory of Constraints (SPROULL, 2009). In a study proposed by Piratesh & Farah during two and half years in 21 industrial plants, the ones that applied TLS methodology obtained 4 times more profit than the plants that applied Lean or Six-Sigma alone and the people involved in the implementation of TLS projects showed more proud of the results obtain by the implementation (PIRASTEH; FOX, 2010), *Figure 4* shows the results in terms of contribution for cost reduction in each methodology:




Figure 4: Contribution for cost reduction in each methodology Source: adapted from Pirasteh and Fox (2010)

The three main methodologies of improving systems continuously present different methods to improve the productive process of the organizations. In *Table 4* is compared the main aspects encountered on each one:



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

Table 4: Six Sigma, Lean and TOC comparative results ((Sproull, 2010), (Stamm, Neitzert, Singh, 2009), (AGI, 2009), (Pirasteh, Farah, 2006))

·	1	Joseph Martin 2000)		
Program	Six Sigma	Lean Maufacturing	Theory of Constraints	
Theory	Reduce variation Remove Waste		Manage Constraints	
Origen	Smith	Toyota (Toyoda, Ohno and Shingo)	Goldratt	
Origen	Motorola and General Electric	and NUMMI (Womack and Jones)	Gordratt	
	1. Define	1. Identify alue	1. Identify constraints	
	2. Me as ure	2.Identify value stream	2. Exploit constraints	
Aplication Guidelines	3. Analyze	3. Flow	3.Subordinate processes	
	4. Improve	4.Pull	4. Elevate constraints	
	5. Control	5.Perfection	5. Repeat cycle	
	Problem focused - Redution of variation	Flow focused - value (material and	Systems constraints	
Focus	Troblem rocasea - Nedation of Variation	information)	,	
	A problem exists	Waste removal will improve	Emphasis on Speed and	
Assumptions	Figures and numbers are valued	business performance	volume	
Assumptions	System output improves if variation	Many small improvements are	Uses existenting systems.	
	in all processes is reduced	better than systems analyses	Process interdependence	
Primary effect	Uniforn process output	Reduce flow time	Fast Througput	
	Less Waste	Less variation	Less inventary/Waste	
	Fast Througput	Uniform output	Througput cost	
	Less inventory	Less inventory	accounting	
Secondary effects	Flutuaction - Performance	New accounting system	Througput - performance	
	measures for managers	Flow- performance measures	measurement system	
	Improved quality	for managers	Improved quality	
		Improved quality		
0.111.1	System interation not considered	Satatiscal or system analysis	Minimal worker imput	
Criticism	Process improved independently	not valuated	Data analysis not valued	
Fi	Deducte a constitution of	Reducing inventory and	Improve Througput	
Finantial Impact	Reducing operating costs	operating costs		
	Organizational struture with	Pull, takt time, heijunka, one		
Distinguishing and value adding	improvement experts(black belt and	piece flow, value stream mapping,	Focus mechanism on constraints	
contribution	grean belt), project oriented,	respect for people	Focus mechanism on constraints	
	quantification of cost saving	respect for people		
Implementation	Medium difficulty	Less difficulty	Major dificulty	
Management level	Middle management and technical level	Workers	Top Management	
Effect on the variation	Reduces	Reduces	Absorbs	
Asperts of the process	Accurate statistics tolls. Specific	Management of the workflow by	Specific metric accounting. Systematic	
Aspects of the process	terminology. Specific experts estruture	JIT. Optimization	focus on constraints	
lat siese	Does not mention	Small batches in the whole system	Larger lots for contraints and smaller for	
Lot sizes	Does not mention	Siliali patches in the whole system	no bottlenecks	
Control of division	Decorat mosting	Kanban triggers the release of	The Drum-buffer-rope methodology is	
Control of production	Does not mention	product	used to release materials	
Doe do sti sa salamaia -	Dans and monting	Detailed planning of the final	Detailed planning for the restriction and	
Production planning	Does not mention	output. The other operations are	less detailed for no bottlenecks	

The complementarities found in each methodology can be synthetized as (PACHECO, 2014; OKIMURA; SOUZA, 2012):

- Lean focus on flow aiming the waste losses and adding value to customer. The application of value flow mapping and problem resolution tools, with the involvement of every hierarchical level, facilitates the cultural change to the continuous improvement of the production systems.
- Six-Sigma focus on the problem that aims the variability and defects reduction originating more stable and predictable processes. Due to his structured and disciplinary statistical tools, to solve complex problems it leads to big improvements in the quality of processes and in the design of new products.



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

■ TOC supports in the identification of system's constraints which should be the

focus of all improvements actions made through Lean and Six-Sigma.

Managing the constraint allows reduction of inventory besides the systematic

improvements. Owning to an accounting system of gains it is possible to have

an appropriated way of measuring the improvements through performance

measures (Gain, Inventory and Operational cost).

2.5. Brief exploration of the main existing TLS models

The existing models have proved to be generic regarding to the destiny where

they can be applied. Although the focus of some models being on productive

systems, they can be adapted to be implemented on project management or on

services.

The most relevant models found are: Bob Sproull's Ultimate Improvement

Cycle (UCI) (SPROULL, 2010), iTLS model introduced by Pirasteh & Farah in 2006

and revised in 2010 book "Profitability with no boundaries" by Pirateh & Fox

(PIRASTEH; FOX, 2010); TOCLSS model introduced by AGI and later developed in

the book VELOCITY (AGI, 2009) and "Excelência 360°" model developed by

Eduardo Moura (MOURA, 2010).

The first two models previously presented were the most used as basis in the

construction of the proposed model in this paper and for that reason they are

presented with more detail.

The iTLS model uses the characteristics of TOC, to identify the constraint and

focus the improvement there to the optimization of the global system, elevate the

constraint and increase gains using the tools of Lean and Six-Sigma in a way to

eliminate waste and variability. It's a continuous improvement model because it

works like a cycle, so after applying the efforts to eliminate the first constraint, return

to the begin to identify a new constraint and continue a cycle. Figure 5 shows the 7

steps existing in the models and the recommended tools and logics to be applied on

each step.

86

http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830




Figure 5: 7 Steps of iTLS model Source: adapted from Pirasteh and Fox (2010)

- a. Mobilize and focus The stakeholders should get involved and the communication needs to be open from the beginning between key-people involved. Efforts are made to find the constraint with TOC tools and the root-cause must be analysed. It's decided where and how the efforts and which should be the expected returns.
- Exploit the constraint Value Stream Mapping Lean tools and new performance indicators are applied at this step.
- c. Eliminate sources of waste After being identified the value, Lean tools are implemented to eliminate waste, increase gains, reduce inventory and operational costs.
- d. Control process variability on this step Six-Sigma tools are applied to reduce the variability in critical processes. It's important to control process variability through statistical tools.
- e. Control supporting activities standards and mechanisms are established to keep critical processes under control. The processes that feed the constraint must be subordinated to avoid failures in supply the constraint process.
- Remove the constraint and stabilize ensure the correct application of the tools to remove the constraint and stabilize the process.



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

The key to keep the process stable and controlled must lie on the formation of employees. It's necessary to ensure that performance indicators are fulfilled.

g. Revaluate the system – checking if the objectives initially defined were performed and if there is a new constraint. The final situation is compared with the initial one in terms of the appropriate indicators of performance.

Ultimate Improvement cycle combines harmonically the best practices in each of the three main continuous improvement cycles. This integration of TOC, Lean and Six-Sigma generates a powerful and rentable strategy for improving any system. On *Figure 6*, it's presented the model and although appearing complex, it's easy to interpret and follow:




Figure 6: Ultimate Improvement Cycle model Source: Adapted from Sproull (2009)

The model is focused on Goldratt's 5 focus step model, in the 5 principles of Lean and in the 5 steps of DMAIC cycle that conciliate together a continuous



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

improvement model. In *Table 5* each step of UIC model is described and showed the recommended tools to apply on every step:

Table 5: Steps and tools in UIC model

1a) Identity Value Steam, current & next constraint & Performance Metrics  1b) Define, Measure & Analyse waste in current constraint  1c) Define, Measure & Analyse waste in current constraint  2c) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4c) Implement protective controls  4c) Implement protective controls over the flow.  At this phase is characterized the value flow and the constraint identified. Waste, defects and variation are defined, measured and analysed.  Constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  Constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Perform Process Audit & Policy Analysis	Table 5: Steps and tools in UIC model					
1a) Identity Value Steam, current & next constraint & Performance Metrics  1b) Define, Measure & Analyse waste in current constraint  1c) Define, Measure & Analyse waste in current constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3c) Reduce variation and defects in the current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective  4c) Implement protective  4do Implement protective  At this phase is necessary to solve problems and improvements are to stay in the future and cannot be wasted.  - VSM, Flow & Inventory Analysis, Performance Metrics Analysis  - Run Charts, Spaghetti Diagrams, Time & Motion Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Causal Chains  - Plan How to Exploit current constraint  - SS, Processing Time Reduction, Mfg Cells, Standardized Work, Visual Aids  - Problem Solving Roadmap, DOE, Paths of Variation Reduction, Plan How to Subordinate Non-Constraints to current constraint in formation is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.	Sten	Description	Recommended tools and			
current & next constraint & Performance Metrics  1b) Define, Measure & Analyse waste in current constraint  1c) Define, Measure & Analyse waste in current constraint  2c) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  2c) Reduce variation and defects in the current constraint  3c) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4c) Plan How to elevate constraint and define protective controls  4c) Implement protective  4c) Implement protective  4c) Implement protective  At this phase is characterized the value flow and the tonstraint identified. Waste, defects and variation of Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Causal Chains  Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Papacheti Diagrams, Time & Motion Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Spaphetti Diagrams, Time & Motions Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Spaphetti Diagrams, Time & Motions, Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Spapheti Diagrams, Time & Motions, Studies, C & E Diagram, Future State VS Map  - Pareto Charts, Run Charts, Spapheti Diagrams, Time & Motions, Studies, C & E Diagram, Causal Chains  - Plan How to Exploit current constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  - Flan How to Subordinate Non-Constraint Unit Systems  - Plan How to Subordinate Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit & Perform Pro	·	Bescription				
At this phase is characterized the value flow and the constraint identified. Waste, defects and variation are defined, measured and analysed.  1c) Define, Measure & Analyse Variation in current constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective  At this phase is characterized the value flow and the constraint constraint constraint characterized the value flow and the constraint dit characterized the value flow and the constraint dit constraint defects and variation are defined, measured and analysed.  Causal Chains  - Pareto Charts, Run Charts, C & E Diagram, Causal Chains  - Plan How to Exploit current constraint  - Plan How to Exploit current constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to state VS Map  - Pareto Charts, Run Charts, Cas E Diagram, Causal Chains  - Plan How to Exploit current constraint sturit ocurrent constraint.  - SS, Processing Time Reduction, Mfg Cells, Standardized Work, Visual Aids  - Problem Solving Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraint Constraint ocurrent constraint.  - Improve Flow & Partial Line Balance (Time & Mon-Constraint and define protective controls  - Plan How to elevate constraint and define protective controls  - Plan How to elevate constrain	1 · · · · · · · · · · · · · · · · · · ·		-			
the process will became more trustful, predictable and constraint constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  1c) Define, Measure & Analyse and the constraint identified. Waste, defects and variation and analysed.  1c) Alefacts and variation ostudised waste, defects and variation are defined, measured and analysed.  1c) Analyse  1c) Analyse  1c) Analyse  1c) Analyse  1c) Analyse  1c) Analyse  1c) Analyse waste in current constraint identified. Waste, defects and variation studitienticle. Waste, defects and variation studitientientientientientientientientientie			Analysis, Performance			
Analyse waste in current constraint in constraint in current constraint in information is optimized. It's necessary to solve problems that affect the consistency of the flow.  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement pro	Performance Metrics	At this phase is	Metrics Analysis			
Analyse waste in current constraint  1c) Define, Measure & Analyse  Variation in current constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  2c) Reduce variation and defects in the current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4danalyse  4defects and variation and analysed.  4c) Elevate variation in current constraint if required  4danalyse  4dana	1h) Define Measure &	characterized the value flow	- Run Charts, Spaghetti			
The process will became more trustful, predictable and constraint constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraints  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4dination and analysed.  4c) Let Datanta variation and analysed.  4c) Define, Measure & Date, measured and analysed.  4c) Elevate the constraint and analysed.  4c) Elevate the constraint if required  4c) Implement protective  4c) Implement protective and analysed.  4c) Implement protective and analysed.  4c) Implement protective  4c) Implement protective  4c) Implement protective and analysed.  4c) Implement protective and cannot be wasted.  4c) Implement protective  4c) Implement protective Sharks and analysis  4c) Implement protective		and the constraint identified.	Diagrams, Time & Motion			
1c) Define, Measure & Analyse Variation in current constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  Analyse  Causal Chains  - Plan How to Exploit current constraint  - 5S, Processing Time Reduction, Mfg Cells, Standardized Work, Visual Aids  - Problem Solving Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraints to current constraint information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  4c) Implement protective  - Pareto Charts, Run Charts, Run Charts, C & E Diagram, Causal Chains  - Plan How to Exploit current constraint  - 5S, Processing Time Reduction, Mfg Cells, Standardized Work, Visual Aids  - Problem Solving  Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraints to current constraint and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.		Waste, defects and variation	Studies, C & E Diagram,			
Analyse Variation in current constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  Analysis  Constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  Constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Charts, C & E Diagram, Causal Chains  - Plan How to Exploit current constraint -5S, Processing Time Reduction, Mfg Cells, Standardized Work, Visual Aids  - Problem Solving Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraint constraint - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint and define protective controls  - Plan How to elevate constraint and define protective controls  - Plan How to elevate constraint and define protective controls  - Perform Capacity  Analysis and Cost/Benefit Analysis  - Perform Process Audit &	Constraint	are defined, measured and	Future State VS Map			
Variation in current constraint  2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  2c) Reduce waste and Cycle Time on current constraint  Constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Constraint is improved and stabilitation is improved and stabilized in simultaneous.  The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  Optimize Buffer Size and Time & Non-Constraint Pull Systems  Plan How to Subordinate Non-Constraint Endough Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint and define protective controls  Perform Capacity Analysis and Cost/Benefit Analysis  Perform Process Audit &	1c) Define, Measure &	analysed.	- Pareto Charts, Run			
2a) Plan How to Exploit current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective controls  4c) Implement protective  4c) Implement protective protective prot	Analyse		Charts, C & E Diagram,			
current constraint  2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protect	Variation in current constraint		Causal Chains			
Constraint is improved and stabilized in simultaneous. The process will became more trustful, predictable and consistent.  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c	2a) Plan How to Exploit		- Plan How to Exploit			
2b) Reduce waste and Cycle Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective  4c) Implement protective  4c) Implement protective  2c) Reduce variation and define protective and Establish Flow  3stabilized in simultaneous. The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to solve problems that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  The flow of materials and information is optimized. It's necessary to constraint and define protective controls  - Plan How to Subordinate Non-Constraint and Elevate Constraint and It in the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint and define protective controls  - Plan How to elevate constrain	current constraint		current constraint			
Time on current constraint  2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The process will became more trustful, predictable and consistent.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and information is optimized. It's necessary to solve problems that affect the constraint of the flow.  The flow of materials and information is optimized. It's necessary to s		Constraint is improved and	- 5S, Processing Time			
Column	2b) Reduce waste and Cycle	stabilized in simultaneous.	Reduction, Mfg Cells,			
2c) Reduce variation and defects in the current constraint  3a) Plan How to Subordinate Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  2c) Reduce variation and and consistent.  3d) And consistent.  4 - Problem Solving Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraints to current constraint to constraint in soptimized. It's necessary to solve problems that affect the consistency of the flow.  4 - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint Pull Systems  4 this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  4 - Problem Solving Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraints to current constraint to constraint - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint and define protective controls  - Plan How to elevate constraint and define protective controls  - Preform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	Time on current constraint	The process will became	Standardized Work, Visual			
defects in the current constraint  3a) Plan How to Subordinate Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  At this phase is necessary to stay in the future and cannot be wasted.  Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraints to current constraints to current constraint to constraint so current constraint and constraint if required  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Roadmap, DOE, Paths of Variation Reduction  - Plan How to Subordinate Non-Constraints to current constraint to current constraint to current constraint to constraint and constraint and constraint Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint and define protective controls  - Plan How to elevate constraint and define protective controls  - Plan How to Subordinate Non-Constraints to current constraint and constraint and constraint Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint and define protective controls  - Plan How to elevate constraint and define protective controls  - Perform Capacity  Analysis and Cost/Benefit Analysis  - Perform Process Audit &		more trustful, predictable	Aids			
Constraint  3a) Plan How to Subordinate Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective  4do Implement protective protecti	2c) Reduce variation and	and consistent.	- Problem Solving			
3a) Plan How to Subordinate Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective  4c) Implement protective  4d)	defects in the current		Roadmap, DOE, Paths of			
Non-Constraints to current constraint  3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  At this phase is necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Non-Constraints to current constraint  - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	constraint		Variation Reduction			
The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  The flow of materials and information is optimized. It's necessary to solve problems that affect the consistency of the flow.  The flow of materials and constraint in soptimized. It's necessary to solve problems that affect the consistency of the flow.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  The flow of materials and constraint - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	3a) Plan How to Subordinate		- Plan How to Subordinate			
3b) Reduce processing Time and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint required  4c) Implement protective  information is optimized. It's necessary to solve problems that affect the consistency of the flow.  1 - Improve Flow & Partial Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint Pull Systems  1 - Plan How to elevate constraint and define protective controls  1 - Perform Capacity Analysis and Cost/Benefit Analysis  2 - Perform Process Audit & Perform Process Audit &	Non-Constraints to current		Non-Constraints to current			
and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  1	constraint	The flow of materials and	constraint			
and Establish Flow  3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Line Balance (Time & Motion Study)  Optimize Buffer Size and Time & Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	2h) Dadusa processing Time	information is optimized. It's	- Improve Flow & Partial			
3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  4c) Implement protective  that affect the consistency of the flow.  At the flow.  Optimize Buffer Size and Time & Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	, ,	necessary to solve problems	Line Balance (Time &			
3c) Implement DBR, constraint buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  Time & Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  insurance that all changes and improvements are to stay in the future and cannot be wasted.  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	and Establish Flow	that affect the consistency of	Motion Study)			
buffer and Pull System  4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Find & Non-Constraint Pull Systems  - Plan How to elevate constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	2a) Implement DPD constraint	the flow.	Optimize Buffer Size and			
4a) Plan How to elevate constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  - Plan How to elevate constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	7 .		Time & Non-Constraint			
constraint and define protective controls  4b) Elevate the constraint if required  4c) Implement protective  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Constraint and define protective controls  - Perform Capacity Analysis and Cost/Benefit Analysis - Perform Process Audit &	buller and Pull System		Pull Systems			
At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  At this phase is necessary to insurance that all changes and improvements are to stay in the future and cannot be wasted.  Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	4a) Plan How to elevate		- Plan How to elevate			
4b) Elevate the constraint if required  4c) Implement protective  insurance that all changes and improvements are to stay in the future and cannot be wasted.  insurance that all changes and improvements are to stay in the future and cannot be wasted.  - Perform Capacity Analysis and Cost/Benefit Analysis - Perform Process Audit &	constraint and define	At this phase is passes to	constraint and define			
4b) Elevate the constraint if required  4c) Implement protective  and improvements are to stay in the future and cannot be wasted.  - Perform Capacity Analysis and Cost/Benefit Analysis  - Perform Process Audit &	protective controls		protective controls			
required stay in the future and cannot be wasted.  Analysis and Cost/Benefit Analysis  Analysis  - Perform Process Audit &	4b) Floyate the constraint if		- Perform Capacity			
4c) Implement protective be wasted. Analysis  - Perform Process Audit &	· · · · · · · · · · · · · · · · · · ·	•	Analysis and Cost/Benefit			
4c) Implement protective - Perform Process Audit &	required	· ·	Analysis			
controls to sustain the gains Policy Analysis	4c) Implement protective	De wasieu.	- Perform Process Audit &			
	controls to sustain the gains		Policy Analysis			

Source: adapted from Sproull (2009)

#### 3. A TLS MODEL TO PRODUCTION SYSTEM IMPROVEMENT

According to Sproull, the key of success of integrated TLS models it's in the first place to identify the constraint, and then to decide how to exploit the constraint applying the appropriate Lean and Six-Sigma tools and in the third place



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

subordinating all the rest to the constraint and finally, if necessary, breaking the constraint with monetary investment (SPROULL, 2009) .

The proposed new model ment to grant flexibility in a way that could be applied on any productive system even if it was previously improved by a Lean and/or Six-Sigma project before (SILVA, 2015). A simplified sketch of the proposed TLS model is presented in *Figure* 7




Figure 7: Simplified Sketch of TLS proposed model

The model presented in the previous figure can suit as roadmap for the implementation of a continuous improvement project. As each project is different when applying the model, it could be necessary to adapt it depending on the output obtained at the end of each step. The model is flexible and there are points where it's required to take decisions and in some systems, it's possible to skip any step if the tools and logics indicated to implement at that phase are already correctly applied.

Next, on this chapter every step of the proposed TLS model is described in detail with the tools and logics recommended to be used at each step.

### 3.1. Analyse System and Identify Constraint – Figure 8




Figure 8: Step 1 of TLS proposed model



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

After identifying the system and its frontiers, the leader responsible for the implementation of TLS project should characterize it thoroughly in a way to obtain full knowledge about its operation. To get to Constraint's identification it's recommended to:

- Design process diagram and obtained all information necessary to build a VSM in order to understand the value of the existing flow in current system and determine the existing Lead Time.
- Promote a real system simulation, if possible, placing it at the maximum capacity to evaluate the evolution of inventory before each step of the process. This assumes that it's operating only during normal working hours and every process pushes WIP to the next process of the system and operators work at a normal rhythm during all the simulation.

When comparing the results of the two previous tools it is identified and validate with reliability system's constraints. All the efforts and improvement focus must stay, at this moment in the Constraint. This process must be analysed with more detail and a team must be mobilized to decide the approach and how to exploit the constraint.

#### 3.2. Exploit Constraint – Figure 9




Figure 9: Step 2 of TLS proposed model

On this step of the proposed TLS model it is necessary to identify and measure Waste (*Muda*). Some possibly logical tools to which can be resorted are:

Study motion with Spaghetti Diagram;



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

 Go to Gemba to detect possible opportunities in 5S and if visual aid is appropriate;

- Check the needs for Standardized work or losses in tool exchanges (changeovers);
- Check if performance metrics and OEE are being correctly measured;
- Compare VSM current State with pretended Future State and plan and implement continuous improving Kaizen events;

Simultaneously to the identification of waste it's necessary to characterize and identify variability in the constraint. The recommended logics and tools to apply are:

- Apply Voice of Costumer, Run Charts, Check sheets and MSA;
- Create Pareto Charts to identify main causes of variability;
- Study causes and effects with Ishikawa Diagram and 5 Whys;
- Make gage R&R studies;
- Study potential impact of defects reduction.

Now it's possibly to answer the question 2a: "If there is LSS improvement opportunities?" In case of the system being already too exploited, the solution is to go to next step of the model and subordinate the others processes to the constraint. Otherwise depending on the opportunities found before, it's chosen where to act and that corresponds to question 2b. In case of finding improvement opportunities that can help reducing waste, some recommended tools are:

- Apply 5S and improve section's visual aid;
- Implement SMED;
- Allocate machines, organize work and reduce unnecessary motions;
- Standardize and normalize changes:
- Implement continuous flow and reduce Lead Time;
- Create needed indicators.

For the variability opportunities found, the Six-Sigma tools and logics recommend to apply are:

- Making opportunity flow diagram and Matrix FMEA;
- Implementing Statistical Process Control resourcing to DOE, Control Charts and
- Process Capacity;
- Studying equipment reliability;



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

 Giving formation to operator about maintenance, stoppages and variability and defects reduction:

 Reducing DPMO (Defects per Million Opportunities) until it gets close to level 6 of Sigma.

# 3.3. Subordinate System to the Constraint – Figure 10




Figure 10: Step 3 of TLS proposed model

After implementing Lean and/or Six-Sigma improvements the next step is to check if DBR and Pull are already being correctly applied in the system. If the correct tools are in use, than it's necessary to make the whole system using them properly. The Kanban and Buffer should get optimized before constraint in a way that the bottleneck stays always fed with materials to avoid unnecessary stoppages.

#### 3.4. Revaluate Constraint and Elevate Constraint's Performance – Figure 11




Figure 11: Step 4 & 5 of TLS proposed model

At this step, the Constraint needs to be revaluated. In case the process now fulfils Takt Time, this means that its capacity is superior to the current demand rate than it closes the first continuous improvement cycle.

In this transaction between cycles, it's important to keep the improvement active and critical attitude to avoid deterioration of the good practices achieved.



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

To identify new constraint of the second improvement cycle it should be made an actualization of the VSM or another simulation with the new parameters of the current situation. Internal audits, with focus on the control of the improvements applied are recommended, to avoid the process to become a constraint again.

On the other hand, if the constraint still can't keep up with Takt Time it is required to go to step 5 of the model. To elevate constraint's performance at this moment, monetary investment can became the only solution. These investments can be done through:

- Buying new machines and equipment;
- Hiring more operators;
- Changing plant layout;
- Solving external factors to the system;
- Searching for better technology and innovation.

The entire model is shown in figure 12:




Figure 12: TLS model to Production System Improvement



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

# 4. RESULTS OF TESTING THE TLS PROPOSED MODEL ON A LEAN PRODUCTIVE SYSTEM

The proposed TLS model was tested in a Lean productive system of an important Portuguese manufacturer where a three year old Lean Program was implemented.

The organization wanted to maintain a Lean as a continuous improvement methodology, but it showed total openness to experiment other continuous improvement methodologies or integration of others like a TLS.

In the *Table 6* it's described which were the tools and logics used in each one of the phases of the model and what the expected impact in the system under study.

Table 6: Tools, Logics and impact expected impact in each one of the phases of the proposed model

proposed model					
Step	Tools and Logics	Expected Impact			
Characterize system and identify constraint	Process diagram Nominal capacity of every Process Lead Time calculation VSM and Current State Real system simulation	Incial characterization of the system Add value Determinations of the points where are inventory accumulation Constraint identification			
2a) Identify opportunities for improvement LSS	Observe GEMBA Spaghetti Diagram Detection of 5S opportunities and visual management failures Needs of Standard Work Comparison of Current state vs Future State Pareto Diagram of defects before and after constraint Ishikawa Diagram	Characterization of MUDA and variability Verification the existance of opportunities LSS			
2b) - Exploit Constrain - Apply LSS	OEE and other KPI's Improvement in 5S and Visual Mangement Improvement of Mizumashi cycle Work organization Standard Work SPC DPMO Mesurement of Dowtime	Reduction of waste Redution/elimination of variability			
Subordinate the System to the Constrain	Drum - Buffer - Rope	System submitted to the rhythm of Constraint			
4 )Revaluate Constraint	Compare actual system performende with <i>Takt Time</i> Update <i>VSM</i>	Process isn't Constraint of the system New Constrain			
5) Elevate Constraint	Budget necessary to elevate Constraint (inthis case isn't necessary)	Investement in the process to eliminate de Constraint			

In the first step of the model two different techniques have been used to identify the



constraint:

http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

# Real system simulation – Figure 13




Figure 13: WIP variation before process

Table 7: Trend line equation of variation of WIP before process

WIP before:	Trend line equation	Slope
Process 1		
Process 2	y = 0.399x + 8.408	0,399
Process 3	y = -0.129x + 48.150	-0,129
Process 4	y = -0.362x + 38.255	-0,362
Process 5	y = 1,426x + 13,29	1,426
Process 6	y = 0.127x + 6.769	0,127

After analysing the *Table 7* it is possible to conclude that the constraint is located in process 5, because it's in this stage that the trend line of WIP has greater slope.

# VSM – Cycle Time

Table 8: System Cycles time

	Process 1	Process 2	Process 3	Process 4	Process 5	Process 6
Cycle Time (s/piece)	31,19	33,67	33,89	32,53	39,09	35,08

In process 5 the Cycle Time is longer – *Table 8*, so it's possible to conclude that the constraint is located at this step of the system.

The conclusions obtained about system's constraints were equal in both methods and it was possibly to define with reliability the existing first improvement cycle's constraint. That process was analysed with more detail and a team was assigned with the task of focusing on process improvement.

http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

After the constraint was exploited corresponding to the second step of the proposed TLS model and several Lean Six-Sigma (LSS) opportunities were identified. On those identified and characterized opportunities for waste and variability reduction it was applied the most appropriate Lean and Six-Sigma tools to solve them – *Table 7*.

After improving the constraint with LSS, it was verified if Pull logic was implemented in the system and if DBR was applied properly before the constraint. There was no need to make any changes in the study case system because Pull and DBR were already well applied and the existing Kanban and buffers were well optimized.

At this moment it was possibly to revaluate constraint found in the first improvement cycle. *Table 9* compares the values encountered for Cycle Time in seconds to produce one piece on every process at the initial conditions that the system was found (October 2014) with the values obtained at the moment of constraint's revaluation (April 2015):

Table 9: Comparison of system's Cycle Time (seconds to produce one piece)

	Process 1	Process 2	Process 3	Process 4	Constraint	Process 6
Initial Cycle Time (October 2014)	31,19	33,67	33,89	32,53	39,09	35,08
Cycle Time (April 2015)	29,80	29,84	29,66	31,72	26,48	29,09

From the table above, it is possible to conclude that the constraint became one of the most efficient processes in the system and it is also possible to notice that all the other processes in the system improved due to the leverage created by the reduction of constraint's Cycle Time avoiding delays and waiting for materials provision.

In the initial conditions that the study case was found the Cycle Time calculated for the bottleneck was 39,09 seconds to produce one piece and when revaluated after the LSS improvements it was only required 26,48 seconds/ piece. This corresponds to a reduction of over 32% in Cycle Time on the constraint just by the application of the suitable LSS tools.

Calculated Takt Time corresponding to the rate of costumers demand was establish at 33,88 seconds/ piece which means that the constraint fulfils successfully the Takt Time demanded by system's clients.



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

Table 10 shows some performance indicators results in terms of Productivity and Quality in the two months when LSS improvements occurred (January and February 2015) and on the two following months after the first cycle improvements (March and April 2015) on constraint:

Table 10: Performance indicators on constraint

Productivity		Quality			
Average of daily processed quantity (pieces/ day)  OEE average (%)		Defects average (%)	Stoppage time due to malfunctions (hours)		
	Januar	y 2015			
2.894	62,17%	9,7%	198h		
	Februa	ry 2015			
3.130	68,13%	10,8%	91h30		
	March	2015			
3.217	76,88%	9,2%	29h30		
April 2015					
3.175	77,07%	8,5%	14h15		

With this obtained results it was possible to close the first improvement cycle of the proposed TLS model. It was not necessary to elevate constraint's performance with financial resourcing corresponding to the fifth step of the model.

In the transition between cycles the creation of a continuous improvement attitude was defined with the Industrial Manager. For that reason the former constraint was kept under control, a meeting between the improvement team about constraint situation kept being realized once a week and it was implemented internal audits in the whole system, with special attention on Capacity-Constrained resources found at the first improvement cycle.

So a second improvement cycle was needed, starting by the updating of the previous VSM with the new data collected. A new improvement cycle begins.

#### 5. MAIN CONCLUSIONS

Reviewing of continuous improvement systems it's possible to verify that from the existing systems found at state of art, the reported to bring better results for managers are the ones that integrate the methodologies Theory of Constraints, Lean production and Six-Sigma in a single improvement project.

This paper proposed a TLS model that shows flexibility to be applied in any system. To test the proposed hypothesis it was decided to implement it in an



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

important Portuguese manufacturer Lean productive system. The application of a TLS model demonstrate to be not more difficult than the implementation of a Lean or Six-Sigma project alone, because the focus of a TLS project only need to stay on constraint's sector instead of being on the whole system.

It's possible to observe results, even in the first improvement cycle which means that is highly recommend apply TLS projects for short-term results. The constraint found went from being the most inefficient process to become one of the most efficient and also all the others processes benefit from the improvements corresponding in a general reduction of Cycle Time.

There is still a need to validate the proposed model with further discussion and in new real systems to make the implementation. Continuous improvement projects should be taken care with a pro-active attitude and need to be maintained with protective measures to avoid a deterioration of the good results obtained.

#### REFERENCES

AGI (2009) Combining Lean, Six Sigma, and the Theory of Constraints to Achieve Breakthrough Performance, **White Papper**, **Goldratt Institute**, Disponível em <a href="https://www.goldratt.com">www.goldratt.com</a>. Acesso em 15 de Maiol de 2017.

ANTONY, J.; BANUELAS, R. (2002) A strategy for survival, **Manufacturing Engineer**, v. 80, p.119–121.

COX, J.; SCHLEIER, J. (2010) **Theory of Constraints**: Handbook, McGraw-Hill, New York.

DAVIES, J.; MABIN, V. (2009) Theory of Constraints, **Decision Line**, v. 40, n. 2, p. 9-12

GOLDRATT, E.; COX, J. (2004) **The goal**: A process of ongoing improvement, Third Revised Edition. The north riverpress, Great Barrington, Massachusett.

JACOBS, R.; CHASE, B.; AQUILANO, J. (2009) **Operations and Supply Management**, McGraw-Hill International Edition, New York.

KHANDEKAR, A.; SULAKHE, V. (2014) Six Sigma - The Revival of TQM. International Journal of Mechanical Engineering and Robotics Research, v. 3, p. 50-58.

LUCAS, D.; TENERA, A. (2014) Input Analysis in Simulation: A Case Study Based on the Variability in Manufacturing Lines, **Advances in Intelligent Systems and Computing**, v. 280, p. 465-477.

MOURA, E. (2010) The Need to Integrate TOC, Lean, Six Sigma and Management by Processes, proceedings of Theory of Constraints International Certification Organization Conference, TOCICO



http://www.ijmp.jor.br v. 10, n. 1, January - Ferbuary 2019

ISSN: 2236-269X

DOI: 10.14807/ijmp.v10i1.830

OKIMURA, L.; SOUZA, F. (2012) Análise dos Modelos de Integração das Abordagens Teoria das Restrições, Produção Enxuta e Seis Sigma: Um Estudo Teórico. **VIII Brazilian Congress of Excellence in Management**.

PACHECO, D. (2014) Teoria das Restrições, Lean Manufacturing e Seis Sigma: limites e possibilidades de integração, **Production**, v. 24, n. 4, p. 940-956.

PEREIRA, Z.; REQUEIJO, J. (2012) **Qualidade**: Planeamento e Controlo Estatístico de Processos, FFCT-Fundação da Faculdade de Ciências e Tecnologias da Universidade Nova de Lisboa, Lisbon.

PIRASTEH, R.; FARAH, K. (2006) Continuous Improvement Trio: The Top Elements of TOC, Lean, and Six Sigma Make Beautiful Music Together. **APICS Magazine**, v. 16, n. 5, p. 31-33.

PIRASTEH, R.; FOX, R. (2010) **Profitability With no Boundaries**: Focus, reduce waste, contain variability, optimize TOC, Lean, Six Sigma Results. ASQ Quality Press, Wisconsin.

PRETORIUS, P. (2014) Introducing in-between decision points to TOC's five focusing steps, **International Journal of Production Research**, v. 52, n. 2, p. 496-506.

SILVA, L. D. (2015) **Ensaio exploratório de um modelo TLS num Sistema Produtivo Lean**: Caso Equipar. Tese de Mestrado em Engenharia e Gestão Industrial, Universidade Nova de Lisboa – Faculdade de Ciências e Tecnologia, Lisboa

SPROULL, B. (2009) **The Ultimate Improvement Cycle**: Maximizing Profits through the Integration of Lean, Six Sigma, and the Theory of Constraints, CRC Press, Taylor & Francis Group, Boca Raton, Florida.

SPROULL, B. (2010) **The Ultimate Improvement Cycle**: Maximizing Profits through the integration of Lean, Six Sigma and Theory of Constraints, CRC Press, New York, NY.

STAMM, M. L.; NEITZERT, T.; SINGH, D. (2009) TQM, TPM, Lean and Six Sigma – Evolution of Manufacturing methodologies under the paradigm from shift Taylorism/Fordism to Toyotism?, **proceedings of 16th International Annual EurOMA Conference** 2009, Gothenburg, Sweden.

TENERA, A. (2006) Contribuição para a melhoria da gestão da incerteza na duração dos projectos através da teoria das restrições. PhD Thesis. Universidade Nova de Lisboa - Faculdade de Ciências e Tecnologia, Lisbon.

TENNANT, G. (2001) **SIX SIGMA**: SPC and TQM in Manufacturing and Services. Gower Publishing, Ltd New York. pp. 6.

WOMACK, J.; JONES, D. (1996) Beyond Toyota: How to Root Out Waste and Pursue Perfection, **Harvard Business Review**, v. 74, n. 5, p.140-158.

